


BEFORE Match-Machining

AFTER Match-Machining



2017 Mercedes AMG CLS 63

All 4 discs resurfaced in less than 60 minutes

Aftermarket "OEM Quality" Rotor Cost:

Front \$350.87 each / Rear \$198.18 each

Book time to R&R discs: Front 1.6 hours Rear 2.2 hrs.

BEFORE Match-Machining

AFTER Match-Machining



2018 Ford F350

All 4 discs resurfaced in less than 40 minutes

Aftermarket "OEM Quality" Rotor Cost:

Front \$211.65 each / Rear \$142.81 each

Book time to R&R discs: Front 2.0 hours Rear 3.9 hrs.

BEFORE Match-Machining

AFTER Match-Machining



2015 Hyundai Santa Fe

Both front discs resurfaced in less than 20 minutes

Aftermarket "OEM Quality" Rotor Cost:

Front \$95.08

Book time to R&R discs: Front 1.0 hours

BEFORE Match-Machining

AFTER Match-Machining



2018 BMW X5

All 4 discs resurfaced in less than 40 minutes

Aftermarket "OEM Quality" Rotor Cost:

Front \$178.98 each / Rear \$114.35 each

Book time to R&R discs: Front 1.4 hours / Rear 1.6 hrs.

BEFORE Match-Machining

AFTER Match-Machining



BEFORE Match-Machining

AFTER Match-Machining



2016 VW Touareg

All 4 discs resurfaced in less than 40 minutes

Aftermarket "OEM Quality" Rotor Cost:

Front \$119.78 each / Rear \$47.98 each

Book time to R&R discs: Front 1.5 hours Rear 2.6 hrs.

2017 Maserati Ghibli Sq4 Quattroporte AWD

Both front discs resurfaced in less than 20 minutes


Aftermarket "OEM Quality" Rotor Cost:

\$334.99 each

Book time to R&R Front discs: 1.4 hrs.

BEFORE Match-Machining

AFTER Match-Machining



BEFORE Match-Machining

AFTER Match-Machining



2016 Porsche 911 Carrera

All 4 discs resurfaced in less than 40 minutes

Aftermarket "OEM Quality" Rotor Cost:

Front \$210.63 each /Rear \$122.75

Book time to R&R discs: Front 1.8 hours Rear 1.6 hrs.

2018 Dodge Ram 3500 Dually

All 4 discs resurfaced in less than 50 minutes

Aftermarket "OEM Quality" Rotor Cost:

Front \$234.45 each Rear \$168.65 each

Book time to R&R discs: Front 1.6 hours Rear 3.4 hrs.